


# BCN-P5999-1600-B(2303)MEE

## Precautions for Using Safety Products

In a safety system using the CC-Link IE Field safety communication functions, there are cases where the required performance of SIL3/SIL2 cannot be satisfied depending on the combination of system configuration and communication settings.

For details, refer to the following technical bulletin.

 Precautions for Using Safety Products (FA-A-0362)

[www.MitsubishiElectric.com/fa](http://www.MitsubishiElectric.com/fa)

 Download ⇄ Technical Bulletin

**MITSUBISHI ELECTRIC CORPORATION**

HEAD OFFICE: TOKYO BLDG., 2-7-3, MARUNOUCHI, CHIYODA-KU, TOKYO 100-8310, JAPAN  
NAGOYA WORKS: 1-14, YADA-MINAMI 5-CHOME, HIGASHI-KU, NAGOYA 461-8670, JAPAN